

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

GF928  
NNE  
> 1  
1.241 mi.  
6554 ft.

MANHOLE 65087  
WEST ST / SOUTH OF AVE U  
BROOKLYN, NY

NY Spills S106698495  
N/A

Site 1 of 2 in cluster GF

Relative:  
Higher

Actual:  
18 ft.

SPILLS:

Name: MANHOLE 65087  
Address: WEST ST / SOUTH OF AVE U  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0405564 / 2004-08-23  
Facility ID: 0405564  
Facility Type: ER  
DER Facility ID: 86264  
Site ID: 96735  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: D4  
SWIS: 2401  
Spill Date: 2004-08-20  
Investigator: SKARAKHA  
Referred To: Not reported  
Reported to Dept: 2004-08-21  
CID: 73  
Water Affected: Not reported  
Spill Source: Unknown

Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2004-08-21  
Spill Record Last Update: 2004-08-23  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: ERT DESK  
DEC Memo:

"e2mis no 154981 RODREGUEZ #83694 REPRORTS HE FOUND APPROX 3-GALLONS OF UNKNOWN OIL ON APPROX 3 OF MUD IN STRUCTURE. ALSO REPORTS FOUND DRY MUD ON SIDEWALK THAT RUNS APPROX 300' X 10 WIDE DOWN THE STREET TO VILLAGE RD NORTH. (POSSIBLE CABLE WAS PULLED BY CABLE GANG). 1-SAMPLE TAKEN. CLEANUP PENDING TEST RESULT. 8/20/04 1800HRS O.S.BENNY BAMONTE ENVIR OPPS REPORTS THERE IS NO OIL ON SIDE WALK JUST MUD. UPDATE 21-AUG-2004 05:00 HRS. ENVIR. OPER. MECH-A K.HUFFORD REPORTS: DBL. WASHED STRUCTURE WITH BIO-GEN 70. ENVIR. TAG # 44595 REMOVED. CLEANUP COMPLETE 100 "

Remarks: "NO TO ALL 5 QUESTIONS. COMING OFF THE 24-HR PROGRAM DUE TO A SUMP IN THE STRUCTURE (UNSURE IF IT IS AN EARTHEN SUMP OR CONCRETE SUMP) CON ED REF # 154981. CLEAN UP IN PROGRESS."

All Materials:

Site ID: 96735  
Operable Unit ID: 888314  
Operable Unit: 01  
Material ID: 486322  
Material Code: 0066A  
Material Name: unknown petroleum

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported